FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5a




FIG. 5b




FIG. 6




FIG. 7




FIG. 8a




FIG. 8b




FIG. 8c




FIG. 9




FIG. 10





FIG. 11







FIG. 12




a: no pre-loadb: small pre-loadc: large pre-load

Ea: maximum magnetostriction factor with no pre-load
Ec: maximum magnetostriction factor with large pre-load

FIG. 13a

FIG. 13b






FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23 PRIOR ART




FIG. 24 PRIOR ART

